

## PWS Information

**Purpose of this worksheet:** For water systems to document basic system information.

### Facility Information

Water System Name:

**Indian Creek Westridge Community Services District**

PWSID:	Population Served (number of people):	Number of Service Connections:	PWS Type:
<b>1410005</b>	<b>1,030</b>	<b>298</b>	<input type="checkbox"/> CWS <input checked="" type="checkbox"/> NTNCWS

### Mailing Address

Street or P.O. Box:

**P.O. Box 952**

City or Town:	State:	Zip Code:
<b>Bishop</b>	<b>CA</b>	<b>93515</b>

### System Contact Person

Name:	Title:
<b>Terry Tye</b>	<b>General Manager</b>
Telephone:	Email:
<b>760-920-1472</b>	<a href="mailto:tyet47@hotmail.com">tyet47@hotmail.com</a>

Person Who Prepared Inventory (if different from above)

# Inventory Methodology

Enter Date Last Updated: \_\_\_\_\_

**Purpose of this worksheet:** For water systems to document the methods and resources they used to develop and update their inventory.

## Part 1: Historical Records Review

Type of Record	Describe the Records Reviewed for Your Inventory
1. Construction Records and Plumbing Codes <i>Examples: Local ordinance adopting an international plumbing code. Permits for replacing lead service lines.</i>	Inquiries to the Inyo County building department
2. Water System Records <i>Examples: Capital improvement plans. Standard operating procedures. Engineering standards.</i>	SOP. (Added WSS per phone conversation - all service line materials visually verified during valve replacements in 2009 and between 2011-2021).
3. Distribution System Inspections and Records <i>Examples: Distribution system maps. Tap cards. Service line repair/replacement records. Inspection records. Meter installation records.</i>	Direct visualization of all lines during service valve replacement program
4. Other Records	

## Part 2: Identifying Service Line Material During Normal Operations

1. During which normal operating activities are you collecting information on service line material? Check all that apply.

- |  |   |
|--|---|
| <input type="checkbox"/> Water meter reading                           | <input checked="" type="checkbox"/> Water main repair or replacement      |
| <input type="checkbox"/> Water meter repair or replacement             | <input checked="" type="checkbox"/> Backflow prevention device inspection |
| <input checked="" type="checkbox"/> Service line repair or replacement | <input checked="" type="checkbox"/> Other                                 |

If "Other", please explain:

2. Did you develop or revise standard operating procedures to collect service line material information during normal operation? Yes

If "Yes", please describe:

**Direct visualization**

## Part 3: Service Line Investigations

1. Identify the service line investigation methods your system used to prepare the inventory (check all that apply).

- |   |  |
|---|--|
| <input checked="" type="checkbox"/> Visual Inspection                 | <input checked="" type="checkbox"/> Water Quality Sampling - Other |
| <input checked="" type="checkbox"/> Customer Self-Identification      | <input type="checkbox"/> Predictive Models or Statistical Analysis |
| <input checked="" type="checkbox"/> Pipe Dating                       | <input checked="" type="checkbox"/> Interpolation                  |
| <input checked="" type="checkbox"/> Pipe Diameter                     | <input checked="" type="checkbox"/> Interviews                     |
| <input checked="" type="checkbox"/> Water Quality Sampling - Targeted | <input type="checkbox"/> Emerging Methods                          |
| <input type="checkbox"/> Water Quality Sampling - Flushed             | <input type="checkbox"/> Other                                     |
| <input type="checkbox"/> Water Quality Sampling - Sequential          |  |

If "Other" or "Emerging Methods," please explain:

2. If "Predictive Modeling" or "Interpolation," please briefly describe the model and inputs used.

Interpolated data from visual inspection og main to service line connector.

3. How did you prioritize locations for service line materials investigations? For example, did you consider environmental justice and/or sensitive populations, did you use predictive modeling, and/or did you target areas with high number of unknowns?

Direct visualization of every line.

## Detailed Inventory

**Date Last Updated:**

**Purpose of this worksheet:** To provide a template for water systems to track materials for each service line in their distribution system.

**General Instructions:** Each row in this worksheet represents one service line connecting the water main to the customer's plumbing. The columns with the aqua shading are required for the Inventory Summary tab. Note that users can freeze panes to enable them to see the headings and notes when entering data. The worksheet includes examples rows and is formatted for approximately 10,000 entries. Please refer to the red triangle in the upper corner for additional instructions.

Location Information			System-Owned Portion									
Unique Service Line ID	Street Address	Other Locational Identifier	System-Owned Portion Service Line Material Classification	Lead Connector Present?	If Material Anything Other than "Lead" in Column E, Was Material Ever Previously Lead?	Service Line Installation Date	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes
1	453 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
2	274 Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
3	3077 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
4	3083 Morningside Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
5	393 S. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
6	236 Pa Me Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
7	293 N. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
8	3053 Morningside Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
9	2906 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
10	321 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
11	3156 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
12	285 N. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
13	328 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
14	224 Pa Me Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
15	342 Pa Me Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
16	2929 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
17	365 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
18	248 Pa Me Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
19	3075 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
20	291 N. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
21	318 Pa Me Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
22	290 N. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
23	440 S. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
24	2917 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
25	3025 Laurel Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	

To provide a template for water systems to track n

ow in this worksheet represents one service line co  
ne worksheet includes examples rows and is form:

Error Count:  
Rows Missing Information:

Location Information		Customer-Owned Portion							Entire Service Line Material Classification (if error or "Missing Information" appears, ensure columns are filled correctly. See instructions)
Street Address	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes	
453 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	7/19/2009		Non-lead
274 Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	7/19/2009		Non-lead
3077 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	7/20/2009		Non-lead
3083 Morningside Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	7/21/2009		Non-lead
393 S. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	7/23/2009		Non-lead
236 Pa Me Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	7/24/2009		Non-lead
293 N. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	7/25/2009		Non-lead
3053 Morningside Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	7/26/2009		Non-lead
2906 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	7/27/2009		Non-lead
321 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	7/28/2009		Non-lead
3156 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	7/29/2009		Non-lead
285 N. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	7/30/2009		Non-lead
328 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	7/31/2009		Non-lead
224 Pa Me Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/1/2009		Non-lead
342 Pa Me Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/2/2009		Non-lead
2929 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/3/2009		Non-lead
365 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/4/2009		Non-lead
248 Pa Me Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/5/2009		Non-lead
3075 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/6/2009		Non-lead
291 N. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/7/2009		Non-lead
318 Pa Me Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/8/2009		Non-lead
290 N. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/9/2009		Non-lead
440 S. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/10/2009		Non-lead
2917 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/11/2009		Non-lead
3025 Laurel Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/12/2009		Non-lead

Unique Service Line ID	Street Address	Other Locational Identifier	System-Owned Portion Service Line Material Classification	Lead Connector Present?	If Material Anything Other than "Lead" in Column E, Was Material Ever Previously Lead?	Service Line Installation Date	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes
26	430 Pa Me Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
27	354 Pa Me Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
28	406 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
29	2930 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
30	406 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
31	333 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
32	378 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
33	3084 S. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
34	3130 S. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
35	2918 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
36	3038 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
37	3051 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
38	366 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
39	3023 Indian Creek Drive, Bsihop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
40	430 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
41	250 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
42	243 N. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
43	2978 Mesquite Road Bishop, CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
44	223 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
45	3129 S. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
46	264 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
47	307 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
48	2966 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
49	299 N. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
50	441 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
51	254 N. Tumlweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
52	265 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
53	2956 W. Line Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
54	2951 Morningside Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
55	296 N. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
56	2966 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	

Street Address	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes	Entire Service Line Material Classification (if error or "Missing Information" appears, ensure columns are filled correctly. See instructions)
430 Pa Me Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/13/2009		Non-lead
354 Pa Me Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/14/2009		Non-lead
406 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/15/2009		Non-lead
2930 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/16/2009		Non-lead
406 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/17/2009		Non-lead
333 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/18/2009		Non-lead
378 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/19/2009		Non-lead
3084 S. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/20/2009		Non-lead
3130 S. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/21/2009		Non-lead
2918 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/22/2009		Non-lead
3038 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/23/2009		Non-lead
3051 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/24/2009		Non-lead
366 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/25/2009		Non-lead
3023 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/26/2009		Non-lead
430 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/27/2009		Non-lead
250 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/28/2009		Non-lead
243 N. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/29/2009		Non-lead
2978 Mesquite Road Bishop, CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/30/2009		Non-lead
223 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	8/31/2009		Non-lead
3129 S. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/1/2009		Non-lead
264 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/2/2009		Non-lead
307 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/3/2009		Non-lead
2966 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/4/2009		Non-lead
299 N. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/5/2009		Non-lead
441 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/6/2009		Non-lead
254 N. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/7/2009		Non-lead
265 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/8/2009		Non-lead
2956 W. Line Street, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/9/2009		Non-lead
2951 Morningside Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/10/2009		Non-lead
296 N. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/11/2009		Non-lead
2966 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/12/2009		Non-lead

Unique Service Line ID	Street Address	Other Locational Identifier	System-Owned Portion Service Line Material Classification	Lead Connector Present?	If Material Anything Other than "Lead" in Column E, Was Material Ever Previously Lead?	Service Line Installation Date	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes
57	3030 Cedar Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
58	235 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
59	297 N. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
60	2942 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
61	161,163,165,167 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
62	377 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
63	3063 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
64	249 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
65	234 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
66	355 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
67	345 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
68	3011 Morningside Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
69	3106 Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
70	389 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
71	331 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
72	3065 Morningside Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
73	3060 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
74	3041 Morningside Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
75	454 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
76	3076 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
77	412 S. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
78	376 S. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
79	3127 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
80	430 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
81	306 Pa Me Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
82	230 N. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
83	464 S. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
84	3035 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
85	286 N. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
86	290 Pa Me Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
87	2930 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	

Street Address	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes	Entire Service Line Material Classification (if error or "Missing Information" appears, ensure columns are filled correctly. See instructions)
3030 Cedar Street, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/13/2009		Non-lead
235 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/14/2009		Non-lead
297 N. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/15/2009		Non-lead
2942 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/16/2009		Non-lead
161,163,165,167 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/17/2009		Non-lead
377 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/18/2009		Non-lead
3063 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/19/2009		Non-lead
249 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/20/2009		Non-lead
234 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/21/2009		Non-lead
355 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/22/2009		Non-lead
345 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/23/2009		Non-lead
3011 Morningside Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/24/2009		Non-lead
3106 Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/25/2009		Non-lead
389 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/26/2009		Non-lead
331 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/27/2009		Non-lead
3065 Morningside Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/28/2009		Non-lead
3060 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/29/2009		Non-lead
3041 Morningside Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	9/30/2009		Non-lead
454 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/1/2009		Non-lead
3076 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/2/2009		Non-lead
412 S. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/3/2009		Non-lead
376 S. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/4/2009		Non-lead
3127 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/5/2009		Non-lead
430 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/6/2009		Non-lead
306 Pa Me Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/7/2009		Non-lead
230 N. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/8/2009		Non-lead
464 S. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/9/2009		Non-lead
3035 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/10/2009		Non-lead
286 N. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/11/2009		Non-lead
290 Pa Me Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/12/2009		Non-lead
2930 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/13/2009		Non-lead



Unique Service Line ID	Street Address	Other Locational Identifier	System-Owned Portion Service Line Material Classification	Lead Connector Present?	If Material Anything Other than "Lead" in Column E, Was Material Ever Previously Lead?	Service Line Installation Date	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes
88	3072 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
89	3087 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
90	277 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
91	245 N. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
92	429 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
93	3142 S. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
94	3028 Laurel Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
95	417 S. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
96	265 N. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
97	280 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
98	3134 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
99	3120 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
100	279 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
101	2990 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
102	418 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
103	205 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
104	3023 Morningside Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
105	2990 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
106	247 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
107	366 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
108	454 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
109	441 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
110	453 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
111	3115 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
112	340 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
113	3064 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
114	3011 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
115	2954 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
116	231 N. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
117	2954 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
118	3117 S. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	

Street Address	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes	Entire Service Line Material Classification (if error or "Missing Information" appears, ensure columns are filled correctly. See instructions)
3072 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/14/2009		Non-lead
3087 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/15/2009		Non-lead
277 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/16/2009		Non-lead
245 N. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/17/2009		Non-lead
429 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/18/2009		Non-lead
3142 S. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/19/2009		Non-lead
3028 Laurel Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/20/2009		Non-lead
417 S. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/21/2009		Non-lead
265 N. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/22/2009		Non-lead
280 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/23/2009		Non-lead
3134 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/24/2009		Non-lead
3120 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/25/2009		Non-lead
279 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/26/2009		Non-lead
2990 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/27/2009		Non-lead
418 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/28/2009		Non-lead
205 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/29/2009		Non-lead
3023 Morningside Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/30/2009		Non-lead
2990 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	10/31/2009		Non-lead
247 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/1/2009		Non-lead
366 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/2/2009		Non-lead
454 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/3/2009		Non-lead
441 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/4/2009		Non-lead
453 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/5/2009		Non-lead
3115 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/6/2009		Non-lead
340 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/7/2009		Non-lead
3064 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/8/2009		Non-lead
3011 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/9/2009		Non-lead
2954 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/10/2009		Non-lead
231 N. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/11/2009		Non-lead
2954 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/12/2009		Non-lead
3117 S. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/13/2009		Non-lead

Unique Service Line ID	Street Address	Other Locational Identifier	System-Owned Portion Service Line Material Classification	Lead Connector Present?	If Material Anything Other than "Lead" in Column E, Was Material Ever Previously Lead?	Service Line Installation Date	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes
119	384 S. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
120	225 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
121	246 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
122	405 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
123	405 S. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
124	418 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
125	472 Pa Me Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
126	389 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
127	2957 Birch Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
128	3106 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
129	3096 S. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
130	276 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
131	237 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
132	208 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
133	238 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
134	2978 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
135	442 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
136	442 Pa Me Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
137	268 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
138	3043 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
139	3012 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
140	357 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
141	2942 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
142	204 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
143	3077 Morningside Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
144	3036 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
145	442 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
146	2941 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
147	3075 S. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
148	2905 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
149	291 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	

Street Address	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes	Entire Service Line Material Classification (if error or "Missing Information" appears, ensure columns are filled correctly. See instructions)
384 S. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/14/2009		Non-lead
225 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/15/2009		Non-lead
246 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/16/2009		Non-lead
405 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/17/2009		Non-lead
405 S. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/18/2009		Non-lead
418 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/19/2009		Non-lead
472 Pa Me Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/20/2009		Non-lead
389 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/21/2009		Non-lead
2957 Birch Street, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/22/2009		Non-lead
3106 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/23/2009		Non-lead
3096 S. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/24/2009		Non-lead
276 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/25/2009		Non-lead
237 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/26/2009		Non-lead
208 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/27/2009		Non-lead
238 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/28/2009		Non-lead
2978 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/29/2009		Non-lead
442 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	11/30/2009		Non-lead
442 Pa Me Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/1/2009		Non-lead
268 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/2/2009		Non-lead
3043 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/3/2009		Non-lead
3012 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/4/2009		Non-lead
357 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/5/2009		Non-lead
2942 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/6/2009		Non-lead
204 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/7/2009		Non-lead
3077 Morningside Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/8/2009		Non-lead
3036 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/9/2009		Non-lead
442 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/10/2009		Non-lead
2941 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/11/2009		Non-lead
3075 S. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/12/2009		Non-lead
2905 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/13/2009		Non-lead
291 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/14/2009		Non-lead

Unique Service Line ID	Street Address	Other Locational Identifier	System-Owned Portion Service Line Material Classification	Lead Connector Present?	If Material Anything Other than "Lead" in Column E, Was Material Ever Previously Lead?	Service Line Installation Date	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes
150	316 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
151	3012 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
152	365 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
153	405 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
154	3144 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
155	3065 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
156	207 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
157	2977 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
158	3041 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
159	644 W. Line Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
160	3050 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
161	3024 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
162	266 Pa Me Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
163	226 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
164	294 N. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
165	3066 Morningside Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
166	3029 E. Cedar Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
167	3035 Morningside Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
168	2907 Birch Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
169	429 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
170	2953 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
171	319 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
172	390 Pa Me Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
173	3105 S. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
174	484 Pa Me Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
175	2918 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
176	3089 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
177	309 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
178	343 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
179	3141 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
180	206 Pa Me Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	

Street Address	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes	Entire Service Line Material Classification (if error or "Missing Information" appears, ensure columns are filled correctly. See instructions)
316 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/15/2009		Non-lead
3012 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/16/2009		Non-lead
365 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/17/2009		Non-lead
405 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/18/2009		Non-lead
3144 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/19/2009		Non-lead
3065 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/20/2009		Non-lead
207 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/21/2009		Non-lead
2977 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/22/2009		Non-lead
3041 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/23/2009		Non-lead
644 W. Line Street, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/24/2009		Non-lead
3050 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/25/2009		Non-lead
3024 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/26/2009		Non-lead
266 Pa Me Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/27/2009		Non-lead
226 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/28/2009		Non-lead
294 N. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/29/2009		Non-lead
3066 Morningside Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/30/2009		Non-lead
3029 E. Cedar Street, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	12/31/2009		Non-lead
3035 Morningside Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2010		Non-lead
2907 Birch Street, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/2/2010		Non-lead
429 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/3/2010		Non-lead
2953 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/4/2010		Non-lead
319 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/5/2010		Non-lead
390 Pa Me Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/6/2010		Non-lead
3105 S. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/7/2010		Non-lead
484 Pa Me Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/8/2010		Non-lead
2918 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/9/2010		Non-lead
3089 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/10/2010		Non-lead
309 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/11/2010		Non-lead
343 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/12/2010		Non-lead
3141 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/13/2010		Non-lead
206 Pa Me Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/14/2010		Non-lead

Unique Service Line ID	Street Address	Other Locational Identifier	System-Owned Portion Service Line Material Classification	Lead Connector Present?	If Material Anything Other than "Lead" in Column E, Was Material Ever Previously Lead?	Service Line Installation Date	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes
181	295 N. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
182	2905 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
183	3084 Morningside Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
184	222 Wildrose Lane, Bishop CA 92514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
185	408 Pa Me Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
186	3078 Morningside Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
187	3054 Morningside Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
188	3118 S. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
189	3153 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
190	330 Pa Me Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
191	267 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
192	304 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
193	3094 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
194	2965 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
195	298 N. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
196	289 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
197	406 Pa Me Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
198	288 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
199	3154 S. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
200	378 Pa Me Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
201	417 Wildrose Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
202	3054 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
203	3100 Indain Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
204	2989 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
205	3103 Indain Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
206	278 Pa Me Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
207	416 S. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
208	366 Pa Me Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
209	3024 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
210	392 S. Tumbleweed Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	
211	3046 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2009	

Street Address	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes	Entire Service Line Material Classification (if error or "Missing Information" appears, ensure columns are filled correctly. See instructions)
295 N. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/15/2010		Non-lead
2905 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/16/2010		Non-lead
3084 Morningside Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/17/2010		Non-lead
222 Wildrose Lane, Bishop CA 92514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/18/2010		Non-lead
408 Pa Me Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/19/2010		Non-lead
3078 Morningside Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/20/2010		Non-lead
3054 Morningside Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/21/2010		Non-lead
3118 S. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/22/2010		Non-lead
3153 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/23/2010		Non-lead
330 Pa Me Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/24/2010		Non-lead
267 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/25/2010		Non-lead
304 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/26/2010		Non-lead
3094 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/27/2010		Non-lead
2965 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/28/2010		Non-lead
298 N. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/29/2010		Non-lead
289 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/30/2010		Non-lead
406 Pa Me Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/31/2010		Non-lead
288 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/1/2010		Non-lead
3154 S. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/2/2010		Non-lead
378 Pa Me Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/3/2010		Non-lead
417 Wildrose Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/4/2010		Non-lead
3054 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/5/2010		Non-lead
3100 Indain Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/6/2010		Non-lead
2989 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/7/2010		Non-lead
3103 Indain Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/8/2010		Non-lead
278 Pa Me Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/9/2010		Non-lead
416 S. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/10/2010		Non-lead
366 Pa Me Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/11/2010		Non-lead
3024 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/12/2010		Non-lead
392 S. Tumbleweed Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/13/2010		Non-lead
3046 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/14/2010		Non-lead



Unique Service Line ID	Street Address	Other Locational Identifier	System-Owned Portion Service Line Material Classification	Lead Connector Present?	If Material Anything Other than "Lead" in Column E, Was Material Ever Previously Lead?	Service Line Installation Date	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes
212	242 Meadow Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
213	3060 Cedar Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
214	231 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
215	255 Meadow Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
216	317 Pinon Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
217	286 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
218	242 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
219	231 Meadow Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
220	219 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
221	292 Meadow Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
222	3040 W. Line Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
223	308 Pinon Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
224	3040 Birch Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
225	3047 Birch Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
226	266 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
227	292 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
228	218 Meadow Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
229	3082 W. Line Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
230	210 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
231	218 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
232	3055 Birch Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
233	202 Meadow Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
234	299 Meadow Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
235	270 Pinon Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
236	3096 Laurel Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
237	219 Meadow Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
238	305 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
239	269 Pinon Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
240	3046 W. Line Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
241	3080 Laurel Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
242	3054 W. Line Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	

Street Address	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes	Entire Service Line Material Classification (if error or "Missing Information" appears, ensure columns are filled correctly. See instructions)
242 Meadow Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011		Non-lead
3060 Cedar Street, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/2/2011		Non-lead
231 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/3/2011		Non-lead
255 Meadow Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/4/2011		Non-lead
317 Pinon Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/5/2011		Non-lead
286 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/6/2011		Non-lead
242 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/7/2011		Non-lead
231 Meadow Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/8/2011		Non-lead
219 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/9/2011		Non-lead
292 Meadow Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/10/2011		Non-lead
3040 W. Line Street, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/11/2011		Non-lead
308 Pinon Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/12/2011		Non-lead
3040 Birch Street, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/13/2011		Non-lead
3047 Birch Street, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/14/2011		Non-lead
266 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/15/2011		Non-lead
292 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/16/2011		Non-lead
218 Meadow Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/17/2011		Non-lead
3082 W. Line Street, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/18/2011		Non-lead
210 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/19/2011		Non-lead
218 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/20/2011		Non-lead
3055 Birch Street, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/21/2011		Non-lead
202 Meadow Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/22/2011		Non-lead
299 Meadow Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/23/2011		Non-lead
270 Pinon Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/24/2011		Non-lead
3096 Laurel Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/25/2011		Non-lead
219 Meadow Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/26/2011		Non-lead
305 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/27/2011		Non-lead
269 Pinon Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/28/2011		Non-lead
3046 W. Line Street, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/29/2011		Non-lead
3080 Laurel Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/30/2011		Non-lead
3054 W. Line Street, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/31/2011		Non-lead

Unique Service Line ID	Street Address	Other Locational Identifier	System-Owned Portion Service Line Material Classification	Lead Connector Present?	If Material Anything Other than "Lead" in Column E, Was Material Ever Previously Lead?	Service Line Installation Date	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes
243	210 Meadow Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
244	243 Meadow Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
245	3053 Laurel Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
246	291 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
247	254 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
248	3039 W. Birch Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
249	3100 W. Line Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
250	267 Meadow Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
251	287 Meadow Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
252	230 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
253	291 Meadow Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
254	286 Meadow Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
255	296 Pinon Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
256	3063 Birch Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
257	3104 Birch Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
258	3196 W. Line Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
259	3081 Laurel Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
260	196 Meadow Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
261	243 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
262	3040 Laurel Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
263	305 Pinon Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
264	266 Meadow Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
265	275 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
266	3044 Cedar Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
267	298 Meadow Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
268	202 Pinon Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
269	295 Meadow Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
270	307 Birch Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
271	275 Meadow Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
272	255 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
273	267 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	

Street Address	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes	Entire Service Line Material Classification (if error or "Missing Information" appears, ensure columns are filled correctly. See instructions)
210 Meadow Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/1/2011		Non-lead
243 Meadow Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/2/2011		Non-lead
3053 Laurel Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/3/2011		Non-lead
291 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/4/2011		Non-lead
254 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/5/2011		Non-lead
3039 W. Birch Street, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/6/2011		Non-lead
3100 W. Line Street, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/7/2011		Non-lead
267 Meadow Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/8/2011		Non-lead
287 Meadow Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/9/2011		Non-lead
230 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/10/2011		Non-lead
291 Meadow Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/11/2011		Non-lead
286 Meadow Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/12/2011		Non-lead
296 Pinon Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/13/2011		Non-lead
3063 Birch Street, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/14/2011		Non-lead
3104 Birch Street, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/15/2011		Non-lead
3196 W. Line Street, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/16/2011		Non-lead
3081 Laurel Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/17/2011		Non-lead
196 Meadow Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/18/2011		Non-lead
243 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/19/2011		Non-lead
3040 Laurel Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/20/2011		Non-lead
305 Pinon Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/21/2011		Non-lead
266 Meadow Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/22/2011		Non-lead
275 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/23/2011		Non-lead
3044 Cedar Street, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/24/2011		Non-lead
298 Meadow Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/25/2011		Non-lead
202 Pinon Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/26/2011		Non-lead
295 Meadow Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/27/2011		Non-lead
307 Birch Street, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	2/28/2011		Non-lead
275 Meadow Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/1/2011		Non-lead
255 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/2/2011		Non-lead
267 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/3/2011		Non-lead

Unique Service Line ID	Street Address	Other Locational Identifier	System-Owned Portion Service Line Material Classification	Lead Connector Present?	If Material Anything Other than "Lead" in Column E, Was Material Ever Previously Lead?	Service Line Installation Date	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes
274	333 Pinon Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
275	274 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
276	3037 Laurel Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
277	3083 Birch Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
278	3062 W. Line Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
279	3070 W. Line Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
280	274 Meadow Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
281	201 Pinon Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
282	297 Meadow Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
283	302 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
284	254 Meadow Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
285	211 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
286	205 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
287	294 Meadow Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
288	211 Meadow Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
289	287 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
290	230 Meadow Lane, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
291	320 Pinon Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
292	2957 Birch Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
293	2029 E. Cedar Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
294	2096 Indian Creek Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
295	377 Grandview Drive, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
296	2944 W. Line Street, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
297	3038 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	
298	3099 Mesquite Road, Bishop CA 93514		Galvanized	No	No	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	1/1/2011	

Street Address	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes	Entire Service Line Material Classification (if error or "Missing Information" appears, ensure columns are filled correctly. See instructions)
333 Pinon Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/4/2011		Non-lead
274 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/5/2011		Non-lead
3037 Laurel Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/6/2011		Non-lead
3083 Birch Street, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/7/2011		Non-lead
3062 W. Line Street, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/8/2011		Non-lead
3070 W. Line Street, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/9/2011		Non-lead
274 Meadow Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/10/2011		Non-lead
201 Pinon Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/11/2011		Non-lead
297 Meadow Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/12/2011		Non-lead
302 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/13/2011		Non-lead
254 Meadow Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/14/2011		Non-lead
211 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/15/2011		Non-lead
205 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/16/2011		Non-lead
294 Meadow Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/17/2011		Non-lead
211 Meadow Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/18/2011		Non-lead
287 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/19/2011		Non-lead
230 Meadow Lane, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/20/2011		Non-lead
320 Pinon Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/21/2011		Non-lead
2957 Birch Street, Bishop CA 93514	Galvanized	5/13/1905	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/22/2011		Non-lead
2029 E. Cedar Street, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/23/2011		Non-lead
2096 Indian Creek Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/24/2011		Non-lead
377 Grandview Drive, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/25/2011		Non-lead
2944 W. Line Street, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/26/2011		Non-lead
3038 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/27/2011		Non-lead
3099 Mesquite Road, Bishop CA 93514	Galvanized	1960	0.75	Field inspection	Yes	Visual inspection at the meter pit	3/28/2011		Non-lead

# Inventory Summary

Enter Date Last Updated: \_\_\_\_\_

**Purpose of this worksheet:** For water systems to provide a summary of their service line inventory, including information on ownership, inventory format, and the number of service lines for each of the four required materials classifications.

## Part 1. General Information

1. Is this the <b>Initial Inventory</b> or an <b>Inventory Update</b> ?	Select One
2. Who <b>owns the service lines</b> in your system? <i>If other, please explain below.</i>	Select Ownership Type
<b>District</b>	
3. When were lead service lines banned in your system? Reference the state or local ordinance that banned the use of lead in your system.	
1/1/1986	
4. Do you have lead goosenecks, pigtails or connectors in your system?	Select "Yes" or "No" or "Don't Know"

## Part 2. Inventory Format

Describe your inventory format in the space provided below (e.g., the **Detailed Inventory** worksheet, custom spreadsheet, GIS map). Provide the filename and/or web address if applicable.

## Part 3. Inventory Summary Table <sup>1</sup>

If you are using the **Detailed Inventory** worksheet, the classifications you select in the Column "Entire Service Line Material Classification" will be used to calculate the total number of service lines for each of the four material classifications below. Otherwise, enter the number of service lines blue- and aqua colored-cells.

**Table 3.1. Inventory Summary by Ownership**

Service Line Material Classification	Number of Water System Owned Service Lines	Number of Customer Owned Service Lines
Lead	0	0
Galvanized	298	298
Galvanized Requiring Replacement	0	1
Non-Lead - Copper	0	0
Non-Lead - Plastic	0	0
Non-Lead - Other	0	0
Unknown	0	0
<b>TOTAL</b>	<b>298</b>	<b>299</b>

**Table 3.2. Inventory Summary Total**

Service Line Material Classification	Definition	Total
Lead	Any portion of the service line is known to be made of lead.	0
Galvanized Requiring Replacement (GRR)	The service line is not made of lead, but a portion is galvanized and the system is unable to demonstrate that the galvanized line was never downstream of a lead service line.	0
Non-Lead	All portions of the service line are known NOT to be lead or GRR through an evidence-based record, method, or technique.	298
Lead Status Unknown	The service line material is not known to be lead, GRR, or non-lead line. For the entire service line or a portion of it (in cases of split ownership), there is no evidence to support material classification.	0
Lead Gooseneck/Fitting	A short section of piping, typically not exceeding two feet, which can be bent and used for connections between rigid service piping.	0
<b>Total Number of Service Lines</b>		<b>298</b>

**Notes**

This summary table is for reporting material for the entire service line connecting the water main to the customer's plumbing. See the Section 4 of the Inventory Instructions or Exhibit 2-2 of U.S. EPA's Guidance for Developing and Maintaining a Service Line Inventory (US EPA, 2022).

# Public Accessibility Documentation

Enter Date Last Updated:

**Purpose of this worksheet:** For systems to provide documentation to states on how they met the public accessibility requirements of the LCRR.

1. Select the location identifiers that you use for your service line inventory. Check all that apply.

- Address
- Street
- Block
- Intersection
- Landmark
- GPS Coordinates
- Other

If "Other", please describe:

2. Does **every service line** have a location identifier?

Select "Yes" or "No"

If "No", explain. Remember that location identifiers are required for service lines that are lead and galvanized requiring replacement.

Yes

3. How are you making your inventory publicly accessible? Check all that apply. Remember that if your system serves > 50,000 people, you **must** provide the inventory online.

- Interactive online map
- Static online map
- Online spreadsheet
- Printed service line map
- Printed tabular data
- Information on water utility mailings or newsletter
- Hard copy information available in water system office
- Other

If "Other", please describe: